

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200207723-1

IN RE APPLICATION OF: U.S. Patent No. 7,100,065

USPTO CONFIRMATION CODE: 9217

APPLICATION NO.: 10/630,182

FILED: Jul. 30, 2003

EXAMINER: Chun Cao

GROUP ART UNIT: 2115

FOR: CONTROLLER ARRANGEMENT FOR SYNCHRONIZER DATA TRANSFER
BETWEEN A CORE CLOCK DOMAIN AND BUS CLOCK DOMAIN EACH
HAVING ITS OWN INDIVIDUAL SYNCHRONIZING CONTROLLER

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/630,182, now Patent Number 7,100,065.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025.

All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

On the face page, in field (54), in column 1, in “Title”, line 2, delete “SYNCHRONIZER” and insert - - SYNCHRONIZING - -, therefor.
(Examiner’s amendment dated Jun. 14, 2006, page 2, line 9)

In column 1, line 2, delete “SYNCHRONIZER” and insert - - SYNCHRONIZING - -, therefor.
(Examiner’s amendment dated Jun. 14, 2006, page 2, line 9)

In column 10, line 49, delete “b2c_valid ff” and insert - - b2c_valid_ff - -, therefor.
(Specification filed on Jul. 30, 2003, page 23, line 1)

In column 16, line 66, in Claim 9, delete “sync ratio” and insert - - sync_ratio - -, therefor.
(Amendment to claims filed on Apr. 13, 2006, page 10, in Claim 9, line 4)

In column 17, line 48, in Claim 11, delete “signet” and insert - - signal - -, therefor.
(Amendment to claims filed on Apr. 13, 2006, page 12, in Claim 11, line 16)

In column 18, line 25, in Claim 14, after “block” delete “;”.
(Amendment to claims filed on Apr. 13, 2006, page 15, in Claim 14, line 3)

In column 18, line 65, in Claim 19, delete “b0_set” and insert - - b0_sel - -, therefor.
(Amendment to claims filed on Apr. 13, 2006, page 17, in Claim 19, line 9)

In column 19, line 32, in Claim 22, delete “N/m \geq 1” and insert - - N/M \geq 1 - -, therefor.
(Amendment to claims filed on Apr. 13, 2006, page 19, in Claim 22, line 8)

In column 20, lines 12-13, in Claim 26, delete “sync ratio” and insert - - sync_ratio - -, therefor.
(Amendment to claims filed on Apr. 13, 2006, page 21, in Claim 26, line 11)

In column 20, line 43, in Claim 29, after “generating a” delete “skew state” and insert - - skew_state - -, therefor.
(Amendment to claims filed on Apr. 13, 2006, page 23, in Claim 29, line 3)


In column 20, line 55, in Claim 30, delete “synch0” and insert - - syncb0 - -, therefor.
(Amendment to claims filed on Apr. 13, 2006, page 23, in Claim 30, line 5)

In column 20, line 57, in Claim 30, delete "signals." and
insert -- signals to said core clock synchronizer controller portion. --, therefor.
(Amendment to claims filed on Apr. 13, 2006, page 23, in Claim 30, lines 6-7)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

12/15/2005
DATE


Name: Steven L. Webb
Registration No.: 44,395

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY
Intellectual Property Administration
P.O. Box 272400
Fort Collins, Colorado 80527-2400

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Page 1 of 2

PATENT NO. : 7,100,065

APPLICATION NO. : 10/630,182

ISSUE DATE : Aug. 29, 2006

INVENTOR(S) : Richard W. Adkisson

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face page, in field (54), in column 1, in "Title", line 2, delete "SYNCHRONIZER" and insert - - SYNCHRONIZING - -, therefor..

In column 1, line 2, delete "SYNCHRONIZER" and insert - - SYNCHRONIZING - -, therefor.

In column 10, line 49, delete "b2c_valid ff" and insert - - b2c_valid_ff - -, therefor.

In column 16, line 66, in Claim 9, delete "sync ratio" and insert - - sync_ratio - -, therefor.

In column 17, line 48, in Claim 11, delete "signet" and insert - - signal - -, therefor.

In column 18, line 25, in Claim 14, after "block" delete ",".

In column 18, line 65, in Claim 19, delete "b0_set" and insert - - b0_sel - -, therefor.

In column 19, line 32, in Claim 22, delete "N/m \geq 1" and insert - - N/M \geq 1 - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY
 Intellectual Property Administration
 P. O. Box 272400
 Fort Collins, Colorado 80527-2400

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Page 2 of 2

PATENT NO. : 7,100,065

APPLICATION NO. : 10/630,182

ISSUE DATE : Aug. 29, 2006

INVENTOR(S) : Richard W. Adkisson

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 20, lines 12-13, in Claim 26, delete "sync ratio" and insert -- sync_ratio --, therefor.

In column 20, line 43, in Claim 29, after "generating a" delete "skew state" and insert -- skew_state --, therefor.

In column 20, line 55, in Claim 30, delete "synch0" and insert -- syncb0 --, therefor.

In column 20, line 57, in Claim 30, delete "signals." and insert -- signals to said core clock synchronizer controller portion. --, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY
Intellectual Property Administration
P. O. Box 272400
Fort Collins, Colorado 80527-2400

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.